Coated linings - Touch up











Damaged linings that require immediate repair to prevent substrate deterioration. We recommend a double layer protective coating.

1. Surface preparation acc. to SepcoTech standards, over the affected area.

2. Apply first layer of SepcoTech Super Guard Coating over the damaged areas.

3. Allow semi-curing.

4. Apply second layer of SepcoTech Super Guard Coating.

5. Allow curing.

Note: In case of heavy pitting, use the SepcoTech Super Metal Filler to obtain the original superstructure.

Includes AI generated images